

BE SAFE FIRE PROTECTION LTD

CERTIFICATE

Be Safe Fire Protection

111 Meadway
Dunstable
Beds
LU6 3JT

01582 475843

On 27th March 2014 have serviced the
Fire Appliances
In accordance with BS 5306: Part 3 2009
As detailed in the Inspection Report

Instalec

Unit 2 Greenwood Court
Ramridge Road
Luton
Beds
LU2 0TN

Foam Extinguisher: 1
Carbon dioxide Extinguisher: 1

Fire Appliances should be checked at least once every month for signs of discharge / lost pressure (if gauge is fitted) / damage / correct location as recommended by British Standards